

within these variations, further scrutiny was not necessary, whereas if we went outside of these variations, then we would have to go the nitty gritty details of cause (i.e., whether it was due to the modifications).

On page 20, Condition 24, as a matter of note: Opacity (continuous opacity monitoring systems; COMs) is measured at the scrubber inlet, not in the stack. Also, our CEMs measure CO₂, not O₂.

The PTE Table on Page 21 was discussed earlier.

Rand Crafts
Intermountain Power Service Corp
rand-c@ipsc.com
435-864-6494
435-864-0994 Fax